

CMD3-2060 Series

Congratulations on the purchase of your new Magnaflux CMD3-2060 Magnetic Particle Inspection Machine! This guide will help you install and set-up your new Magnaflux machine.

If you have any questions, please contact your local Magnaflux Authorized Service Center or call Magnaflux Customer Service at 847-657-5300.



Getting Started


The manual is shipped with the unit in electronic format wrapped in a green bubble wrap mailer within the Accessories Box. In the manual is an extensive step by step process of how to assemble the enclosure and attach it to the unit.




Operating Manual and Drawings

Set-Up

Back of Unit:



Incoming Power Connection



Chassis Ground Connection

1. A minimum of two feet is required at both ends and the rear of the inspection unit to ensure adequate space for servicing (removing machine panels and accessing the circulating pump) and ventilation.
2. A firm, reasonably level floor capable of supporting the inspection unit and the materials awaiting inspection.
3. Adequate space to accommodate a black light inspection canopy (Optional), material storage, material movement and access to the materials.
4. A power source of the proper voltage, frequency and phase (as designated on the **Magnaflux Data Plate** located on headstock end of inspection unit) capable of providing current per the nameplate. Connect the incoming power to the Incoming Power Connection located inside the unit on the back side. Attach the Chassis Ground wire to the inside of the unit to the Chassis Ground Connection Screw. Follow all local electrical codes for wiring. It is highly recommended that an electrical fused disconnect be installed on the headstock side of the unit—Either on the wall behind the unit or on a pedestal near the unit. See page 3 for correct fuse sizes.

Electrical Input:

Input Volts AC	Phase	Full Load (Amps)	Recommended Line Fuse (Amps)	Recommended Wire Size (AWG)
208	N/A	N/A	N/A	N/A
230	3	N/A	N/A	N/A
380	3	450	225	3/0
415	3	430	225	3/0
460	3	400	200	2/0
575	3	325	200	2/0

The equipment can be fused based on less than the maximum amperage draw due to the duty cycle. Refer to NEC Code Section 630.31 Ampacity of Supply Conductors and Table 630.31 (A) (2) Duty Cycle Multiplication Factors for Resistance Welders (NPF National Electric Code 2011). Some areas refer to 2 phase instead of 1 phase. The incoming power goes directly to an isolation transformer so the unit will operate identically on 1 or 2 phase power.